










# USER SKIDS ROUNDS

DATE: 3/4/2003 TIME:                      TECH:                     

CAT NAME/ LOCATION	PUMP DISCHARGE OR SYSTEM PRESSURE	SYSTEM FLOW RATE	SYSTEM LEVEL/ FILL	N2 PRESSURE	SYSTEM FILTER DP	POLISHING FILTER DP	POLISHING RESISTIVITY	SYSTEM RESISTIVITY	SUPPLY TEMP.	UV
SRI-CAT <b>SECTOR 1</b> SRVC 3/4	120	N/A	Good	Good	0	1	N/A	17.14	N/A	
SRI-CAT <b>SECTOR 2</b> SRVC 5/6	Off line	N/A	Good		N/A	N/A	N/A	N/A	N/A	
SRI-CAT <b>SECTOR 3/4</b> SRVC 7/8	140	51.5	Good	Good	0	0	17.7	15	N/A	
MU-CAT <b>SECTOR 6</b> CL 82	125	5.8	Good	Good	0	0	17.2	16.06	N/A	
MHATT-CAT <b>SECTOR 7</b> SRVC 9/10	90	N/A	Good		0	0	8.81	7.85	N/A	
IMM-CAT <b>SECTOR 8</b> CL 88	70	15.3	Good	Good	0	0	15.44	13.91	N/A	
CMC-CAT <b>SECTOR 9</b> SRVC 11/12	130	4.9	Good	Good	0	0	21.73	15.78	N/A	
BESSRC-CAT <b>SECTOR 11</b> SRVC 13/14	80	72	Good		0	N/A	N/A	N/A	N/A	
<b>SECTOR 15</b> SRVC 17/18	80	26.9	Good	Good	0	0	5.55	5.43	N/A	
SBC-CAT <b>SECTOR 19</b> SRVC 21/22	40	70	Good		0	0	N/A	N/A	67	
SER-CAT <b>SECTOR 22</b> CL130	50	60	Good		0	N/A	N/A	N/A	60	N/A
SGX-CAT <b>SECTOR 31</b> SRVC 33/34	N/A	12.4	Good		0	N/A	N/A	N/A	N/A	
<b>SECTOR 32</b> CL 160	160	N/A	Good		0	0	23.27	17.27	N/A	
UNI-CAT <b>SECTOR 33</b> SRVC 35/36	120	N/A	Good		N/A	0	9.13	8.64	N/A	
<b>SECTOR 34</b> CL 166	142	134	Good		N/A	0	N/A	16	N/A	