










# USER SKIDS ROUNDS

DATE: 3/7/2003 TIME: \_\_\_\_\_ TECH: \_\_\_\_\_

CAT NAME/ LOCATION	PUMP DISCHARGE OR SYSTEM PRESSURE	SYSTEM FLOW RATE	SYSTEM LEVEL/ FILL	N2 PRESSURE	SYSTEM FILTER DP	POLISHING FILTER DP	POLISHING RESISTIVITY	SYSTEM RESISTIVITY	SUPPLY TEMP.	UV
SRI-CAT <b>SECTOR 1</b> SRVC 3/4	120	N/A	Good	Good	0	1	N/A	17.4	N/A	
SRI-CAT <b>SECTOR 2</b> SRVC 5/6	Off line	N/A	Good		N/A	N/A	N/A	N/A	N/A	
SRI-CAT <b>SECTOR 3/4</b> SRVC 7/8	135	57.4	Good	Good	0	0	15.93	14.44	N/A	
MU-CAT <b>SECTOR 6</b> CL 82	125	5.9	Good	Good	0	0	15.98	15.91	N/A	
MHATT-CAT <b>SECTOR 7</b> SRVC 9/10	90	N/A	Good		0	0	8.75	7.74	N/A	
IMM-CAT <b>SECTOR 8</b> CL 88	70	15.4	Good	Good	0	0	15.09	14.03	N/A	
CMC-CAT <b>SECTOR 9</b> SRVC 11/12	130	48	Good	Good	0	0	21.78	15.8	N/A	
BESSRC-CAT <b>SECTOR 11</b> SRVC 13/14	80	72	Good		0	N/A	N/A	N/A	N/A	
<b>SECTOR 15</b> SRVC 17/18	80	26.7	Good	Good	0	0	5.75	5.44	N/A	
SBC-CAT <b>SECTOR 19</b> SRVC 21/22	35	70	Good		0	0	N/A	N/A	67	
SER-CAT <b>SECTOR 22</b> CL130	45	60	Good		0	N/A	N/A	N/A	60	N/A
SGX-CAT <b>SECTOR 31</b> SRVC 33/34	N/A	12.5	Good		0	N/A	N/A	N/A	N/A	
<b>SECTOR 32</b> CL 160	160	N/A	Good		0	0	23.03	17.34	N/A	
UNI-CAT <b>SECTOR 33</b> SRVC 35/36	120	N/A	Good		N/A	0	8.61	8.33	N/A	
<b>SECTOR 34</b> CL 166	142	134	Good		N/A	0	N/A	15.98	N/A	